

AMENDMENTS TO THE SPECIFICATION

Please replace paragraph 0046 with the following paragraph:

[0046] The motor 504 is attached to the underside of the touchpad 500 and rotates in the same plane as the touchpad 500 rotates. The motor rotation is limited. Two rubber end-stops 5[[6]]06a, b limit the rotation of the motor 504. Preferably, the rotation of the touchpad 500 is limited. In the embodiment shown, since the rotation of the motor 504 is limited and the motor 504 is attached to the touchpad 500, the rotation of the touchpad 500 is limited as well.